Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rud1 Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED:	Bushbaby
BULLETIN NUMBER:	SB005
ORIGIONAL ISSUE DATE:	04-04-02
REVISION DATE:	01-02-19
SUBJECT:	Lower Lift strut attachment bolt length.
APPLICABILITY:	All
COMPLIANCE:	Mandatory.

PROBLEM:

An Inspected Bushbaby was found to have the incorrect bolts installed at the lower lift strut-fuselage point.

SOLUTION:

These bolts must be checked before the next flight.

The correct bolts supplied by KFA will have the shank long enough to not have any thread in the shear area of the joint.

Do not turn the nut up to the shank when setting it.

If it is necessary, up to 3 washers can be used to allow the nut to be correctly set.

Contact the factory if the correct bolts are required.