Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED:	Bushbaby airframes
BULLETIN NUMBER:	SB013
ORIGIONAL ISSUE DATE:	04-04-02
REVISION DATE:	01-11-2026
SUBJECT:	Cracks in firewall tubes due to flexing LNW-13 bracket
APPLICABILITY:	Nose-wheel airframes older than 2002
COMPLIANCE:	Mandatory

Problem: Older nose-wheel Bushbaby frames had a separate bracket in the cockpit, supporting the firewall at the nose-wheel bracket attachment point. If this bracket was left out, cracks developed in the firewall tubes and in the tubes under the floor boards as well.

Solution: Be sure that the LNW-17 V brace bracket is installed in the older nose-wheel air frames.

If it is found that a nose wheel airframe does not have this bracket fitted, a full inspection of the firewall truss as well as the airframe below the floor is required.

Airframes built after 2002 have the bracket welded in.