Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

# SERVICE BULLETIN

| | |
|---|---|
| **AIRCRAFT EFFECTED:** | Bushbaby and Explorer |
| **BULLETIN NUMBER:** | SB016 |
| **ORIGINAL ISSUE DATE:** | 01-10-03 |
| **REVISION DATE:** | 01-11-2026 |
| **SUBJECT:** | 582 engine isolator rubber spacer tube length |
| **APPLICABILITY:** | All fitted with Rotax 582 engines. |
| **COMPLIANCE:** | Mandatory |

**Problem:** The EM-4 engine mount isolation rubber spacer tubes supplied with some 582 engine kits sold before October 2003 were too short at 30mm.

Assembly with these incorrect spacers will cause excessive compression of the isolation rubbers and unwanted engine vibration transmitted through to the rest of the aircraft.

**Solution:** The correct spacer length is 35mm.

If the incorrect spacer tubes were supplied, replace the tubes with the correct length tubes available from KFA.