Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED:	All models
BULLETIN NUMBER:	SB015
ORIGINAL ISSUE DATE:	01-09-02
REVISION DATE:	01-11-2026
SUBJECT:	Horizontal stabilizer attachment tabs broken.
APPLICABILITY:	All serial numbers
COMPLIANCE:	Mandatory

Problem: Forward horizontal stabilizer tabs were found to be broken.

The tabs had been bent in to meet the vertical fin when bolted up.

Solution: Never bend tabs like this. If the space for mounting is slightly too big, insert washers to take up any free space before bolting up tight.