Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED:	**Bushbaby**
BULLETIN NUMBER:	SB001
ORIGIONAL ISSUE DATE:	04-04-02
REVISION DATE:	01-11-2026
SUBJECT:	Tail post insert
APPLICABILITY:	SN001 - SN015
COMPLIANCE:	Mandatory. Before next flight

PROBLEM: According to our records, some of the earliest Bushbabies were manufactured with the tail-post tube not structurally braced.

SOLUTION: Owners of aircraft SN001 - SN015 please contact the factory if this bulletin has not been incorporated.

A 400mm split tube with one welded end is available for insertion into the original tail-post. Tap the split tube into the tail-post with the welded end up until the mid-section of the tail-post is braced.

The tail-post design was changed after SN015.