Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@saplanes.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED: Bushbaby
BULLETIN NUMBER: SB002
ORIGIONAL ISSUE DATE: 04-04-02
REVISION DATE: 01-11-2026
SUBJECT: Axle tube too short.
APPLICABILITY: SN001 - SN015
COMPLIANCE: Mandatory.

PROBLEM: Some of the early Bushbaby landing gear legs were made with the Ø16mm ID axle tubes too short which will not allow proper installation of the wheel and brake in accordance with the build manual.

The correct length for the axle tube is 125mm.

SOLUTION: Contact the factory or turn a bush out of mild steel to make up the correct axle tube length.