Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

# SERVICE BULLETIN

| | |
|---|---|
| **AIRCRAFT EFFECTED:** | Bushbaby |
| **BULLETIN NUMBER:** | SB003 |
| **ORIGIONAL ISSUE DATE:** | 04-04-02 |
| **REVISION DATE:** | 01-11-2026 |
| **SUBJECT:** | Incorrect FBM-B aileron mixer supplied. |
| **APPLICABILITY:** | SN001 - SN015 |
| **COMPLIANCE:** | Mandatory. |

**PROBLEM:** A mistake occurred in setting up the FBM-B aileron mixer jig.

This would cause the ailerons to work the wrong way around.

**SOLUTION:** Contact the factory.

The correct mixer is available.

Cut up and discard the old mixer.