Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED:	All models
BULLETIN NUMBER:	SB014
ORIGIONAL ISSUE DATE:	01-09-02
REVISION DATE:	01-11-2026
SUBJECT:	Axle retaining bolts
APPLICABILITY:	All aircraft with KFA axles.
COMPLIANCE:	Mandatory

Problem: Some axle retaining bolts were found to be too short and sheared at the thread.

Solution: Axle bolts should have the shank protruding from the axle tube by 1mm and be fitted with a washer under the nut.

Remove and inspect the axle retaining bolt at every annual or 100 hour inspection.