Kitplanes for Africa (Pty) Ltd
Port 49 Varkfontein 25IR
Hangar 1
Petit Airport
Rudi Street, Petit
Benoni, 1502

Vat no – 4190250029
AMORG – M715
Office - +27 (0) 11 965 6205

www.kitplanesforafrica.co.za
info@kitplanesforafrica.co.za

SERVICE BULLETIN

AIRCRAFT EFFECTED: Bushbaby
BULLETIN NUMBER: SB021
ORIGINAL ISSUE DATE: 23-12-08
REVISION DATE: 01-11-2026
SUBJECT: Back-plates with axles welded onto them
APPLICABILITY: All Bushbabies with these fitted
COMPLIANCE: Mandatory

Problem: Some of the older Bushbabies were fitted with the brake back plate welded onto the axle forming one unit.

There has been an axle failure where the axle broke at the weld after a hard landing.

Solution: It has been decided that the separate axle and back plate is a better design to promote better axle durability.

Owners who have aircraft fitted with this old design should contact the factory for replacement parts.